

[Pearson Gold Derocker](#)

[Inventory ID #219950]



- Like new condition.
- Deck and bushings: 90 percent.
- Sidewalls: 95 percent.
- All manifolds and sluice run are original.
- Includes 40 hp electric hydraulic pack.
- Location: Northern Canada.
- Contact for more information.

View more [Derockers](#)