

[Warman 12 x 10 FAH Repair Kit](#) **[Inventory ID #83847]**



- Frame plate liner insert (28% chrome).
- Impeller (28% chrome).
- Impeller (28% chrome).
- Throat bushing (28% chrome).
- Volute liner (28% chrome).
- Intake joint ring.
- Volute liner seals (2).
- Discharge joint ring.
- O-rings (4).
- Throat bushing studs (8).
- 3 kits available.