

[Pegson Jaw Crusher Plant](#)

[Inventory ID #183265]



- Year: 2004.
- 26 in. x 44 in. jaw crusher.
- CAT engine.
 - 3900 hours.
- Feed hopper.
- Discharge conveyor.
- Track mounted.
- Reported to be in very good condition.
- Location: North East USA.

Please contact us for more information.

View more [Crushing Plants](#)