

## Sandvik D75KS Rotary Drill [Inventory ID #1401186]



### Sandvik D75KS Rotary Drill

- Make: Sandvik
- Model: D75KS
- Drilling Method: Rotary
- Track Mounted
- Hole Size: 229mm to 279mm (9in to 11in) Diameter Holes
- Multi-Pass Drill for up to 53m (173ft) High Benches
- Pulldown: 334 kN (75,000 lbf)
- Bit Load: up to 409 kN (92,000 lbf)
- Year: 2011
- Condition: Used - Good, General Working Condition
- Hours: 17,555 Hours
  - Major Components Changed-Out:
    - Track Repairs: 4,925.8 Hours (Changed out at 12,629.2 Hours)
    - Compressor: 3,878.2 Hours (Changed out at 13,676.8 Hours)
    - Engine Rebuild: 3,317.6 Hours: (Changed out at 14,237.4 Hours)
    - Rotary Head: 1,544.7 Hours (Changed out at 16,010.3 Hours)
    - Feed Cylinder: 1,351.5 Hours (Changed out at 16,203.5 Hours)
    - Rotation Motors: 711.1 Hours (Changed out at 16,843.9 Hours)
    - Carousel Hanger Bracket: 556.2 Hours (Changed out at 16,998.8 Hours)
  - Tram Hour Reading: 1,346 hours
- Engine: CAT 3412 (760HP)
  - Rebuild Done by Barloworld
  - Fitted with (2) New Starters
  - Fitted with (4) New Batteries
- Compressor: Sullair
  - Model: No. 25
  - Hours: 3,878 Hours
  - New Compressor and Air-End have been Fitted
- Rotary Head:
  - Hours: 1,544.7



- Very Good Condition
- Mast:
  - Mast Pins and Bushes are New
  - Mast Structure in Very Good Condition and Well Looked After
  - (2) New Rotation Motors
  - Mast Slides appear to be in a Very Good Condition, No Deep Marks or Scoring Visible
  - Mast Chains are in a Good Condition and Properly Tensioned
  - Rod Handlers are Working and in Good Condition
- Hydraulic Components:
  - Hydraulic Cylinders are in Good, Working Order
  - Mast Lift Cylinders were Recently Reconditioning and are Basically as New
  - No Evidence of any Scoring on Cylinder Shafts; All Cylinder Seals are Intact
  - All (3) Outriggers are Functional
  - All Hydraulic Motors are in Good Working Order
- Undercarriage:
  - Undercarriage in Very Good Condition, with CAT Sprockets and Rollers from ITR
  - Shoes, Bushes, Idlers, and Rollers are in Very Good Condition
  - Track Repairs were Done by Barloworld
- Safety Devices/Features:
  - Rig is Equipped with Spotlights for Illumination
  - Fire Suppression System - needs Refill and Recertification
- Add-Ons:
  - On-Board Automated Lubrication System
  - Depth Counter
  - Emergency Stop Switches in Cab and Exterior
  
- [View Spec Sheet Below](#)
  
- Location: South Africa

View More [Rotary Drills](#)